


# ST-2A-X

## PINOUT DIAGRAM



OPTICAL PORT (ST, FC)

STATUS INDICATORS

PWR - POWER (GREEN)  
 DIAG - NA  
 TX C/L - TX CARRIER (GREEN) / OVERLOAD (RED)  
 RX C/E - NA  
 SYN - NA  
 VID - NA

AUDIO INPUT

1. (CH.1) AUDIO INPUT-
2. GND
3. (CH.1) AUDIO INPUT+

STATUS INDICATORS

DRX - NA  
 AT1 - (CH.1) AUDIO INPUT  
 CRX - NA

AUDIO INPUT


1. (CH.2) AUDIO INPUT-
2. GND
3. (CH.2) AUDIO INPUT+

STATUS INDICATORS

DTX - NA  
 AT2 - (CH.2) AUDIO INPUT  
 CTX - NA

# SR-2A-X

## PINOUT DIAGRAM



### OPTICAL PORT (ST, FC)

#### STATUS INDICATORS

PWR - POWER (GREEN)  
 DIAG - NA  
 TX C/L - NA  
 RX C/E - RX CARRIER (GREEN) / ERROR (RED)  
 SYN - NA  
 VID - NA

#### AUDIO OUTPUT

1. (CH.1) AUDIO OUTPUT-
2. GND
3. (CH.1) AUDIO OUTPUT+

#### STATUS INDICATORS

DRX - NA  
 AR1 - (CH.1) AUDIO OUTPUT  
 CRX - NA

#### AUDIO OUTPUT

1. (CH.2) AUDIO OUTPUT-
2. GND
3. (CH.2) AUDIO OUTPUT+

#### STATUS INDICATORS

DTX - NA  
 AR2 - (CH.2) AUDIO OUTPUT  
 CTX - NA